

3403067012

001326

US EPA RECORDS CENTER REGION 5



514798

REILLY TAR & CHEMICAL CORPORATION

To: Mr. H. L. Finch - St. Louis Park

Office: Indianapolis

From: T. E. Reilly

Date: October 3, 1969

Subject: EQUIPMENT - ST. LOUIS PARK - REPAIRS TO NO. 16 STILL.
WORK ORDER NO. 243-B

Work Order No. 243-B has been established to cover the necessary repairs to the No. 16 Still which has failed due to a rupture at the 10:00 o'clock position, 12" long, on September 15.

On close examination, it was found that the repair could be effected by welding a 4" plate inside the still the full length between the 9:00 and 11:00 o'clock position.

This work necessitated removing insulation and replacing it.

The estimated cost of the job to remove insulation and the damaged section is \$80.00; cost of boiler plate, labor, and insulation \$900.00, or an over-all job cost of approximately \$1,000.00.

The work will be completed October 10.

Please make all charges for the work to General Ledger Account No. 153-243-B.


SCB:12

cc: Mr. W. A. Justin - St. Louis Park
Mr. R. J. Hennessy - Reilly Lab.
Mr. H. R. Horner - Reilly Lab.
Mr. P. C. Reilly - Office
Mr. R. J. Boyle - Office
Mr. T. J. Ryan - Office
Mr. W. J. Reuel - Office
Mr. S. C. Boyle - Office

Very truly yours,

T. E. Reilly

per S.C. Boyle



220560